

DESIGN / CRAFT FABRIC CORPORATION

WASHING INSTRUCTIONS FOR FR FABRIC

WASH:

- USE SYNTHETIC DETERGENT
- WASH IN WATER NO HOTTER THAN 140°F TO 160°F
- DO NOT USE CHLORINE BLEACH OR FABRIC SOFTENERS

DRY:

- TUMBLE DRY ON MEDIUM HEAT 105°F TO 120°F MAX
- DRY FOR 3 TO 5 MINUTES
- PULL FABRIC OUT BEFORE IT BECOMES TOO HOT